

APPLICATION STORIES

Customer: A manufacturer of packaging equipment

Industry: Packaging

SIC Code: 3565

Location: Minnesota

Department:

Retrofit or OEM: OEM

Machinery Involved: Caser-cases milk cartons

Description of Environment: Washdown with caustic solutions. Also overhung load.

Description of Problem: Shafting would rust, linear ball bearings would fail due to washdown and overhung load.

Solution: Replaced class L shafting with 316 stainless steel. Replaced linear ball bearings with Simplicity.

Customer Reaction to Solution: Stainless shafting and Simplicity bearings have solved their corrosion and lubrication problems.

Documented Cost Savings:

Simplicity Part Used: PWC 12

Qty of Bearings Used:

Date of Installation: 1994

Photos Available: No

Illustrations Available:

Application Write Up Available: Yes

