

APPLICATION STORIES

Customer: Trade Exhibit Manufacturer

Industry: Trade Show Displays

SIC Code:

Location: California

Department:

Retrofit or OEM: OEM

Machinery Involved: 4 parallel vertical shafts were used in an interactive display for children.

Description of Environment: Potential binding on the shaft. Hand operated display was mounted on the 4 shafts.

Description of Problem: Bearings were binding on the shaft.

Solution: Simplicity compensated bearings were used to allow smooth motion.

Customer Reaction to Solution: Customer was pleased to get a long term solution for the display. The kids love the new display.

Documented Cost Savings:

Simplicity Part Used: PN08C

Qty of Bearings Used: 8 per display

Date of Installation: 1994

Photos Available:

Illustrations Available: Yes

Application Write Up Available: Yes

